

BS-7

SIGN:

Danger....

COMMENT:

Sign is faded and illegible.

RECOMMENDATION:

Repaint or replace with standard sign.



BS-8

SIGN:

Boat Barrier Not Installed Danger Dam 8000 Feet Ahead Exit Left Bank.

COMMENT:

Spray painted sign is less effective. Poor condition. Unclear message for "Exit." Less effective font.

RECOMMENDATION:

Replace sign with different lettering and clear "Portage" indicator.